


[

NO. 0373 PRO Wear CARE T-shirt | v-neck | women



Description (measured in cm)	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
A: ½ Chest width	45	47	50	53	56	59	62	66	70	74
E: Front length from high point shoulder	64	66	68	70	72	74	76	78	80	82
H: Shoulder to shoulder	37	38	39.5	41	42.5	44	45.5	47.5	49.5	51.5
K2: Sleeve length - short	19	19.5	20	20.5	21	21.5	22	22.5	23	23.5
L: ½ upper arm width	16.75	17.5	18.5	19.5	20.5	21.5	22.5	23.75	25	26.25

How to measure



Tolerance in cm

A	E	H	K	K2	L
1.5	1.5	1.5	1.5	1	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not after washing. We reserve the right to make mistakes and omissions in the chart. You are always welcome to contact us for further guidance on using our product measurement chart at support@id.dk or tel: +45 97492144