NO. 1510 Cotton bag

Description (measured in cm)	One size
FFF: Width	38
EEE: Height	42
GGG: Depth	12

How to measure



Tolerance in cm

EEE	FFF	GGG
1.5	1.5	1.5

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not after washing. We reserve the right to make mistakes and omissions in the chart. You are always welcome to contact us for further guidance on using our product measurement chart at support@id.dk or tel: +45 97492144